## FOR WIPED FILM EVAPORATION





MONITOR EACH LINE OF A WFE UNIT





Detect D9, Chlorophyll, Lipids, and more in real-time

 $\cdot$  Observe for oddities in either line at the point of collection



Ensures separation of terpenes during terp stripping pass
Ensure that Delta-9 is present in the distillate line during the D9 refining pass
Ensure that contaminates, and minimal amount of Delta-9, are in the residue line

## PROCESS PARAMETER FEEDBACK

Validate that you are operating at the optimal parameters
Tune process parameters, such as flow rate and temperature

